



Set Up - Scratch Start Kit

1 Remove all packaging and check the contents of the box.


2 Fit the Regulator to the outlet of the Argon Cylinder



3 Fit the flow meter to the outlet of the regulator ensuring the sight glass is vertical



4 Connect the gas hose from the torch to the outlet of the regulator



5 Fit the required consumables from the accessory kit

Note :- Not included in the Kit :- Power source, Earth lead, Argon bottle

5 Fit the power cable to the front of the machine in the - socket

